

ICS 43.040.20

CCS T 38



**NATIONAL STANDARD OF THE
PEOPLE'S REPUBLIC OF CHINA**

GB 19151-2003

**Warning triangles for motor vehicle
(English Translation)**

Issued on: May 23, 2003

Implemented on: November 1, 2003

**Issued by: General Administration of Quality Supervision, Inspection and
Quarantine of the People Republic of China**

Table of Contents

What this standard covers	1
Document data	2
Standards quoted by this document	3

What this standard covers

This Chinese standard specifies the warning triangle (hereinafter referred to as warning signs) the technical requirements, test methods, inspection rules. This standard applies to motor vehicles onboard, when used placed on the road, can be a warning signal to indicate circadian suspended vehicle warning devices exist.

Document data

International classification (ICS): 43.040.20.

Chinese classification (CCS): T38.

Estimated length of the Chinese original: 15,125 words.

Adopted international standard: ECE R27, NEQ.

Standards quoted by this document

GB/T 3978-1994; ISO 105-1978