

ICS 17.220.20

CCS N 22



**NATIONAL STANDARD OF THE
PEOPLE'S REPUBLIC OF CHINA**

GB/T 17215.811-2017

**Electricity metering equipment ((a.c.) -- Acceptance inspection
-- Part 11: General acceptance inspection methods
(English Translation)**

Issued on: December 29, 2017

Implemented on: July 1, 2018

**Issued by: General Administration of Quality Supervision, Inspection and
Quarantine of the People's Republic of China, Standardization
Administration of the People's Republic of China**

Table of Contents

Foreword	
1 Scope	
2 Normative references	
3 Terms and Definitions	
3.1 Data Source	
3.2 Sample Type	
3.3 Specifications, Values, and Test Results	
3.4 Inspection Type	
3.5 Type 6 Acceptance Sampling Inspection	
3.6 Relevant Terms of Acceptance Sampling Inspection System	
3.7 Reception criteria	
3.8 Type 8 operating characteristic curve	
3.9 Terms related to operational characteristics	
3.10 Check Out Quality Concept	
3.11 Other Terms	
4 Symbols and Abbreviations	
4.1 Symbol	
4.2 Abbreviations	
5 General rule	
5.1 Acceptance Test Target	
5.2 Acceptance Sampling Plans, Plans and Systems	
5.3 Practical and Economic Advantages of Using Standard Sampling Plans	
5.4 Agreement of All Parties	
5.5 Selection of Sampling Plans and Sampling Plans	
5.6 Considerations for Impact Selection	
5.7 Disqualification and Nonconformance	
5.8 Unqualified classification	
5.9 Operating Characteristics (OC) Curves	
5.10 Producer Risk (PR) and Consumer Risk (CR)	
5.11 AQL, PRQ, LQ, and CRQ	
5.12 Transfer Rules for Normal Inspection, Strict Inspection and Relaxation Inspection	
5.13 Inspection Level	

- 5.14 Sample size code
- 5.15 Inspection Site
- 5.16 Submission of Acceptance Inspection Products
- 5.17 Sample extraction
- 5.18 Batch Acceptability
- 6 100% inspection
 - 6.1 Application of this method
 - 6.2 Batch and Receive Number
 - 6.3 Receiving and not receiving
- 7 Batch-by-lot inspection
 - 7.1 Method Application
 - 7.2 Sample extraction
 - 7.3 Level of inspection
 - 7.4 Sampling plan
 - 7.5 Normal, tightened and relaxed inspections (see 5.12)
 - 7.6 Operating Characteristics (OC) Curves
 - 7.7 Process Average
 - 7.8 Average Outgoing Quality (AOQ)
 - 7.9 Average Quality of Detection (AOQL)
 - 7.10 Consumer Risk (CR)
 - 7.11 Producer Risk (PR)
- 8 Isolated Batch Test
 - 8.1 Application Method
 - 8.2 Provisions Procedure
 - 8.3 Limit Quality
 - 8.4 Procedure A
 - 8.5 Program B
 - 8.6 Rules Received and Not Received
- 9 Batch inspection
 - 9.1 Application Method
 - 9.2 Producer Qualification
 - 9.3 Product Qualification
 - 9.4 Detailed Procedure
- 10 Batch measurement inspection
 - 10.1 Application Method

10.2 Choice Between "s Method" and "sigma Method"	
10.3 Standard Plan	
10.4 Preparation	
10.5 Standard multivariable "s method" program with independent quality characteristics of combination control	
10.6 Independent Characteristics with Combination Control Standard Multivariable "sigma Method"	
10.7 Procedures for Continuous Inspection	
10.8 Normality and Outliers	
10.9 Record	
10.10 Normal, tightened and relaxed inspections (see 5.12)	
10.11 Inspection and Restoration	
10.12 Conversion between "s Method" and "sigma Method"	
10.13 Consumer Protection	
10.14 Operating Characteristic Curve	
10.15 Consumer Risk (CR)	
10.16 Producer Risk (PR)	
Appendix A (Normative) Random Number	
Appendix B (Normative Appendix) Obtaining s or sigma Programs	
References	
Figure 1 Sampling plan and program selection process	
Figure 2 Transfer Rules Figure	
Fig. 3 OC curve of one sampling scheme with AQL=1.0 (normal inspection)	
Fig. 4 OC curve of one sampling scheme with AQL=1.0 (tightened test)	
Fig. 5 Ac=0 sampling scheme OC curve	
Figure 6 Operation curve of a sampling plan for non-critical nonconforming items (Procedure B)	
Figure 7 Normal test OC curve for AQL=1.0	
Figure 8 Strictly Tested OC Curve for AQL = 1.0	
Figure 9 AQL = 1.0 relaxation test OC curve	
Table 1 Number of Acceptances for the 100% Inspection Ac	
Table 2 One-time sampling plan for normal, tightened and relaxed tests (AQL=1.0)	
Table 3 Example 1 (Batch 80, Inspection Level II)	
Table 4 Example 2 (Batch 400, Inspection Level II)	
Table 5 Example 3 (Batch 800, Inspection Level III)	
Table 6 Sampling scheme for key nonconformities (Ac=0)	

Table 7	Secondary sampling plan for normal, tightened and relaxed tests (AQL=1.0)
Table 8	Calculation of Transfer Score
Table 9	One-time sampling OC curve list value of AQL=1.0
Table 10.	Single sampling scheme for Ac=0 List of OC curves (normal inspection)
Table 11	Upper limit of average detection quality (AOQL) for AQL=1.0
Table 12	Average Detection Upper Limit (AOQL) of Ac=0 for Sampling Plans
Table 13	Consumer risk quality (CRQ) 32 for the AQL=1.0 scheme
Table 14	Consumer Risk Quality (CRQ) for Zero Receiver Plan
Table 15	Producer Risk (PR) with AQL=1.0
Table 16	Producer Risk (PR) for Zero Receiver Plan
Table 17	Sampling plans for non-critical nonconformities (Procedure A, LQ=5.0)
Table 18	Sampling Plan for Critical Nonconformities (Procedure A)
Table 19	Receiving Probability of Zero Receiver Scheme
Table 20	One sampling plan for non-critical nonconformities (Procedure B, LQ=5.0)
Table 21	Equivalent sample size for one sampling and subsampling 38
Table 22	Equivalent acceptances for one sampling and subsampling 38
Table 23	Sample size of "s method" and "sigma method" (AQL=1.0)
Table 24	S-method sampling plan
Table 25	Value of alphan
Table 26	"Sigma method" sampling plan
Table 27	Receiving Constants for Relaxation Inspection Qualification
Table 28	The cU value of the control limit on sample standard deviation
Table 29	Normally Tested OC Curve Table Column Values for AQL=1.0
Table 30	Strictly Tested OC Curve Table AQL=1.0 Column Value
Table 31	Relaxation check OC curve table column value 51 for AQL=1.0
Table 32	Consumer Risk Quality of "s Method"
Table 33	Consumer Risk Quality (CRQ) for the sigma Method
Table 34	Producer Risk (s) of "S Method"
Table 35	Producer Risk (PR) for "sigma Method"
Table A.1	Random Number

Foreword

GB/T 17215.8 "Acceptance Inspection of AC Measurement Equipment" is divided into the following three parts.