Chinastandards.org

HB

INDUSTRY STANDARD OF THE PEOPLE'S REPUBLIC OF CHINA

HB 8362-2015

GH4169 thread tolerance zone h7 tolerance 6h threaded rod with cotter pin hole, long thread, small hexagon head bolts

GH4169螺纹公差带6h光杆公差带h7螺纹带开口销孔长螺纹小六角头螺栓

(English Translation)

Issued on: October 10, 2015 **Implemented on: March 1, 2016**

Issued by: Ministry of Industry and Information Technology of the People's Republic of China

Preview: page 1 of 3 shown, 6 in the full document. Complete English PDF, instant download:
https://chinastandards.org/standards/hb-8362-2015

Chinastandards.org

Table of Contents

[Preview only]
1 Scope
2 Normative References
2.1 Terms
3 Terms and Definitions
4 Overview
4.1 General requirements
5 Technical Requirements
6 Calibration conditions
6.1 Environmental conditions
6.2 Measurement standards and other equipment
7 Calibration items and calibration methods
7.1 Calibration Items
7.2 Calibration method
8 Expression of calibration results
9 Recalibration interval

1 Foreword

HB 8362-2015 was issued by Ministry of Industry and Information Technology of the People's Republic of China on 10 October 2015 and has been in force since 1 March 2016.

The HB prefix, without a suffix, marks a mandatory standard: within its scope, compliance is required.

The document runs to 6 pages in English translation.

2 Scope Preview

HB 8362-2015 carries no ICS number and no Chinese Standard Classification code.

This catalogue holds 171 other HB standards.

Of the 65 HB standards that do carry an ICS number, 65 (100%) fall under ICS 49, in the field of aircraft and space vehicle engineering.

Preview: page 2 of 3 shown, 6 in the full document. Complete English PDF, instant download:
https://chinastandards.org/standards/hb-8362-2015

3 About this standard

Issued by: Ministry of Industry and Information Technology of the People's Republic of China

English translation: about 6 pages

Chinese original: about 8,874 characters

4 Related standards

Standards on related subjects:

JB 2293-1978 - Wind tunnel test method of radiator of automobile and tractor

5 Classification and status

Prefix HB: mandatory standard.

Preview: page 3 of 3 shown, 6 in the full document. Complete English PDF, instant download:
https://chinastandards.org/standards/hb-8362-2015