

JB

**INDUSTRY STANDARD OF THE
PEOPLE'S REPUBLIC OF CHINA**

JB/T 7403-1994

Illuminance meters

光照度计

(English Translation)

Issued on: August 23, 1994

Implemented on: May 1, 1995

**Issued by: Ministry of Industry and Information Technology of the
People's Republic of China**

Table of Contents

1 Subject content and scope of application	3
2 Normative references	3
3 Product categories	3
4 Technical requirements	4
5 Test methods	6
6 Inspection rules	16
7 Marking, packaging, transportation, storage	17
CIE photopic spectral light efficiency $V(\lambda)$ with a color temperature of 2856K	19
Additional information	20

1 Subject content and scope of application

This standard specifies the product classification, technical requirements, test methods, inspection rules, marking, packaging, transportation, storage, etc. of illuminometers.

This standard applies to illuminometers whose photometric detectors are silicon photovoltaic cells, silicon photodiodes, selenium photovoltaic cells. An illuminometer whose photometric detector is a photoelectric tube can also make reference to this standard.

2 Normative references

GB 2828 Sampling procedures and tables for lot-by-lot inspection by attributes (Apply to inspection of successive lots or batches)

GB 2829 Sampling procedures and tables for periodic inspection by attributes (Apply to inspection of stability for productive process)

JB 5517 Optical Instrument Electrical Protection basic safety requirements

ZBY 002 Basic environmental conditions and test methods for transportation and storage of instruments

ZBY 003 General technical conditions for instrument packaging

3.1 Product type

Illuminometers are divided into pointer illuminometers and digital illuminometers, according to their reading types.

3.2 Product grade

Product are divided into four grades: standard grade, first grade, second grade, third grade.

4.13 Electrical safety performance

The instrument shall comply with the requirements of JB 5517.

4.14 Storage and transportation environmental conditions

The instrument shall comply with the requirements of ZBY 002 under the conditions of storage, transportation, packaging. The high temperature test shall be +55 °C; the low temperature test shall be -40 °C; the free drop height shall be 250 mm.

5.1.1 Test device

- a. One set of light intensity working reference lamps which have a color temperature of 2856K (used to measure the standard illuminometer);
- b. One set of second grade light intensity standard lamps which have a color temperature of 2856K (used to measure first-, second-, third-grade illuminance meters);
- c. DC voltage regulated power supply and corresponding supporting equipment (I.

Voltage regulated power supply requirements for light intensity working reference lamps: the voltage change shall not be greater than 0.015% and the

5.6.1 Test device

Same as Article 5.1.1 a ~ d of this standard.

5.6.2 Test procedure

Adjust the distance between the light source and the photometric probe on the photometric guide rail, so that the photometric probe can receive nearly 1000 lx illumination. Read out the indicated value of the illuminometer, when irradiating for 10 seconds. Then read out the indicated value of the illuminometer, when continuing irradiating for 30 minutes. Calculate the fatigue error according to formula (11):

Where:

Y(30 min) - The indicated value of the illuminometer when irradiated for 30 minutes, lx;

Y(10 s) - The indicated value of the illuminometer when irradiated for 10 seconds, lx;

f 5 - Fatigue error.

5.7.1 Test device

Same as Article 5.1.1 a ~ d of this standard.

5.7.2 Test procedure

Adjust the distance between the light-emitting surface of the light source and the test surface of the photometric probe on the photometric guide rail. Find the standard illuminance value $X_{\max}$, which is corresponding to the full range of the illuminometer.

Meanwhile read out the indicated value $Y_{\max}$ of the illuminometer. Then move the photometric probe (or light source) to a position which is 1/10 of the full range.

Calculate the standard illuminance value X ; read out the indicated value Y of the illuminometer. At least the nonlinear error of each gear below the 1000 lx range shall be measured. Calculate the nonlinear error of each gear according to formula (12):

Where:

Y - The indicated value of the illuminometer at 1/10 full range, lx;

$Y_{\max}$ - The indicated value of the illuminometer at full range, lx;

X - The standard illuminance value at 1/10 full range, lx;

$X_{\max}$ - The standard illuminance value at full range, lx;

f_6 - Linearity error.

5.8.1 Test device

Same as Article 5.1.1 a ~ d of this standard.

5.8.2 Test procedure

Adjust the distance from the light-emitting surface of the light source to the test surface of the photometric probe on the photometric guide rail. Find the standard illuminance value X (A) of the illuminometer, which is equivalent to that the illuminometer is at 90% of full range when it is at low range (gear A); meanwhile read out the indication value

Y (A) of the illuminometer. Then move the photometric probe (or light source) on the photometric guide rail, to the position where the standard illuminance value is K times higher than X_A . Switch the illuminometer to gear B. Read out the indicated value $Y(B)$.

Calculate the gear shift error according to formula (13):

Where:

5.11.1 Test device

- a. Same as Article 5.1.1 a ~ c of this standard;
- b. Temperature controller.

5.11.2 Test procedure

Place the illuminometer inside the temperature controller, with the indicator facing out the window. Place the standard lamp outside the temperature controller, to illuminate the photometric probe. Control the current of the standard lamp to remain constant and keep the relative position of the illuminometer and the light source constant. Control the temperature respectively at 5 °C, 20 °C, 40 °C, respectively. After maintaining temperature at each gear for one hour, read the indicated value of the illuminometer.

Then calculate according to formula (16).

Where:

T 1 - High temperature, which takes 40 °C;

T 2 - Low temperature, which takes 5 °C;

To - Normal temperature, which takes 20 °C;

Y(T 1) - The indicated value of the illuminometer at 40 °C, lx;

Y(T 2) - The indicated value of the illuminometer at 5 °C, lx;

Y(To) - The indicated value of the illuminometer at 20 °C, lx;

alpha - Temperature coefficient.