

ICS 73.100.10
CCS D 92

MT

**INDUSTRY STANDARD OF THE
PEOPLE'S REPUBLIC OF CHINA**

MT/T 541.2-2007

Replacing MT/T 541.2-1996

**Boom type roadheader overhaul criterion. Part 2: Mechanism
part**

悬臂式掘进机 检修规范 第2部分：机械部分
(English Translation)

Issued on: October 22, 2007

Implemented on: January 1, 2008

**Issued by: National Development and Reform Commission of the
People's Republic of China**

Table of Contents

What this standard covers	1
Document data	2
Standards quoted by this document	3

What this standard covers

This standard specifies the general requirements for cantilevered boring machine mechanical parts repair quality. Ghost of each system component repair methods and requirements. This section applies to the mechanical parts of roadheader maintenance quality assessment and control.

Document data

International classification (ICS): 73.100.10.

Chinese classification (CCS): D92.

Estimated length of the Chinese original: 11,138 words.

Supersedes the earlier edition MT/T 541.2-1996.

Standards quoted by this document

GB/T 3766; GB/T 7935; GB/T 10095.1; GB/T 10095.2; GB/T 10096; GB/T 11365; MT/T 291.1; MT/T 291.2