Chinastandards.org

CCS M 53

SJ

INDUSTRY STANDARD OF THE PEOPLE'S REPUBLIC OF CHINA

SJ 20835-2002

Specification of repair for battlefield reconnaissance radar

战场侦察雷达修理规范

(English Translation)

Issued on: October 30, 2002 **Implemented on: March 1, 2003**

Issued by: Ministry of Industry and Information Technology of PRC

Preview: page 1 of 2 shown, 7 in the full document. Complete English PDF, instant download:
https://chinastandards.org/standards/sj-20835-2002

Chinastandards.org

Table of Contents

What this standard covers 1
Document data 2

What this standard covers

This standard specifies the battlefield surveillance radar (hereinafter referred to as radar) level repair, repair methods and repair process management. This standard applies to battlefield surveillance radar repairs.

Document data

Chinese classification (CCS): M53.

Estimated length of the Chinese original: 11,163 words.

Preview: page 2 of 2 shown, 7 in the full document. Complete English PDF, instant download:
https://chinastandards.org/standards/sj-20835-2002