

ICS 55.080
CCS W 33

SN

**INDUSTRY STANDARD OF THE
PEOPLE'S REPUBLIC OF CHINA**

SN/T 0740-2010

Replacing SN/T 0740-1997

Rules for inspection of gunny bags for import and export

进出口黄麻麻袋检验规程

(English Translation)

Issued on: March 2, 2010

Implemented on: September 16, 2010

Issued by: General Administration of Customs

Table of Contents

- Foreword
- 1 Scope
- 2 Normative references
- 3 Requirements
 - 3.1 Appearance quality requirements
 - 3.2 Internal quality requirements
- 4 Sampling
 - 4.1 Appearance of the test sample
 - 4.2 Internal inspection sampling

Foreword

Instead of the standard SN/T 0740-1997 "exports of jute sacks for the inspection." this standard compared with SN/T 0740-1997, the main changes are as follows.

- Standard name from the "export of jute sacks for the inspection" to "import and export of jute sacks for the inspection";
- Standard overall structure of the changes;
- The scope was revised to apply to the import and export of jute sacks test content;
- Abolition of the "definitions, symbols" section;
- The original standard Chapter 4, "technical requirements" and Chapter 5, "test project" merged into Chapter 3, "Requirements", and subdivided into Chapter 3.1 "Appearance quality requirements" and Chapter 3.2 "Internal quality requirements";
- Sampling program further refined into appearance of the test sample, the size of sacks, needle and thread count density test sample, broken Pub crack strength and quality inspection sampling;
- Increased Chapter 7, "Packaging and Identification";
- Appendix removed content "sack visual inspection condition".

Appendix A of this standard is an informative annex.

This standard is proposed and managed by the National Certification and Accreditation Administration Committee.

This standard is mainly drafted by. People's Republic of China Exit Inspection and Quarantine of Henan, Shandong, People's Republic of China Entry-Exit Inspection and Quarantine Bureau.

1 Scope

This standard specifies the requirements for the import and export of jute sacks, sampling, testing and judging the results.

This standard applies to jute, kenaf as raw materials import and export inspection and woven sacks.

2 Normative references

The following documents contain provisions which, through reference in this standard and become the standard terms. For dated references, subsequent Amendments (not including errata content) or revisions do not apply to this standard, however, encourage the parties to the agreement are based on research Whether the latest versions of these documents. For undated reference documents, the latest versions apply to this standard.

GB/T 2828.1 Sampling procedures for inspection - Part 1. by acceptance quality limit (AQL) retrieval batch inspection sampling plan GB/T 3923.1 Textiles Tensile properties of fabrics - Part 1. breaking force and elongation Strip method Determination of GB/T 4668 woven fabric density

3.1 Appearance quality requirements

Jute sacks should look no defects affect the use, there should be following defects (see Appendix A).

Holes, dilute block, warp, weft, weaving wrong, oil, stitched bad, bad seam and the like.

3.2 Internal quality requirements

The inherent requirements of jute sacks of the following. sack size, conventional mass, Density, needle density, breaking strength. Specific indicators Product requirements by importing countries.

4.1 Appearance of the test sample

Visual inspection of the sample according to GB/T 2828.1 in normal inspection single sampling plan, general inspection level I, acceptance quality limit AQL = 4, sample testing program test are shown in Table 1.

Table 1 Appearance inspection sampling plan

Bulk sample size N number Ac like receiving rejection number Re ≤ 15 2 0 1 16 to 25,301
26 to 90,501 91 ~ 150812 151 ~ 2801312 281 ~ 5002023 501 ~ 12,003,234 ≥ 1201 50 5 6

4.2 Internal inspection sampling

During internal quality control sample, the size of sacks, needle and thread count density of sample testing program are shown in Table 1; breaking force and public