

**INDUSTRY STANDARD OF THE
PEOPLE'S REPUBLIC OF CHINA**

SN/T 3702.2-2013

**Quality conformity evaluation of textiles for import and export.
Sampling method. Part 2: Textile raw materials
(English Translation)**

Issued on: November 6, 2013

Implemented on: June 1, 2014

Issued by: General Administration of Customs

Table of Contents

- Foreword
- 1 Scope
- 2 Normative references
- 3 Terms, definitions and symbols
- 3.1 Terms and Definitions

Foreword

SN/T 3702 "Textiles Import and Export Quality Conformity Assessment Sampling Method" is divided into seven sections.

- Part 1. General;
- Part 2. Textile raw materials;
- Part 3. textile yarn;
- Part 4. woven fabric;
- Part 5. textiles;
- Part 6. clothing;
- Part 7. Special textiles.

This section SN/T 3702 Part 2.

This section drafted in accordance with GB/T 1.1-2009 given rules.

This section proposed and managed by the National Certification and Accreditation Administration Committee.

1 Scope

SN/T 3702 provisions of this part of the sampling program and export of textile raw materials, sampling methods and quantities.

This section applies to sampling inspection and quarantine authorities for import and export of textile raw materials. Import and export inspection and quarantine institutions is the former textile the sampling material procedural rules should be followed, but also as the import and export of textile production enterprises quality control guidance documents.

2 Normative references

The following documents for the application of this document is essential. For dated references, only the dated version suitable for use herein Member. For undated references, the latest edition (including any amendments) applies to this document.

GB/T 1798 Test Method for raw silk GB/T 2828.4-2008 Sampling procedures for inspection - Part 4. Procedures for assessment of declared quality levels GB/T 2828.11-2008 Sampling procedures for inspection - Part 11. Small claims overall level of quality assessment procedures GB/T 6378.4 Sampling Inspection procedures - Part 4. The mean level of declared quality assessment procedures GB/T 8054 measurement standard sampling procedures and tables GB/T 10111 random number generation and its application in product quality sampling in GB/T 16306-2008 declared quality level and retest assessment procedures SN/T 3702.1 Textiles Import & Export quality conformity assessment sampling methods - Part 1. General

3.1 Terms and Definitions

SN/T 3702.1 and define the following terms and definitions apply to this document.

3.1.1

Quality level Verification of the actual overall percent nonconforming, or verification of the actual population mean certain quality characteristics.

3.1.2

Declared quality level Purported value verify the overall level party verification of claims allowed in percent nonconforming, or verification of quality characteristics of a population Mean.

3.1.3

Declared quality level cap upperlimitofdeclaredqualitylevel Overall verification of the claim on the limit level of quality.

3.1.4

Claimed that the lower quality level lowerlimitofdeclaredqualitylevel Overall verification of claims lower limit level of quality.