

ICS 61.020
CCS Y 76

SN

**INDUSTRY STANDARD OF THE
PEOPLE'S REPUBLIC OF CHINA**

SN/T 3702.6-2014

Replacing SN/T 1932.2-2008

**Quality conformity evaluation of textiles for Import and export.
Sampling method. Part 6: Garment
(English Translation)**

Issued on: January 1, 1970

Implemented on: January 1, 1970

Issued by: General Administration of Customs

Table of Contents

Foreword
1 Scope
2 Normative references
3 Terms, definitions and symbols
3.1 Terms and Definitions

Foreword

SN/T 3702 "Textiles Import and Export Quality Conformity Assessment Sampling Method" is divided into seven sections.

- Part 1. General;
- Part 2. Textile raw materials.
- Part 3. textile yarn;
- Part 4. woven fabric;
- Part 5. textiles;
- Part 6. clothing;
- Part 7. Special textiles.

This section SN/T 3702 Part 6.

This section drafted in accordance with GB/T 1.1-2009 given rules.

The partial replacement of SN/T 1932.2-2008 "clothing import and export inspection procedures - Part 2. Sampling." Section compared with the SN/T 1932.2-2008 The main changes are as follows.

- Modify the appearance quality inspection standard sampling methods;
- Increase the statutory requirements for sampling programs;
- Increased regulatory requirements of non-sampling plan.

This section proposed and managed by the National Certification and Accreditation Administration Committee.

1 Scope

SN/T 3702 provisions of this part of the import and export of clothing statutory requirements and non-regulatory requirements of quality inspection sampling plan, the number of samples and so on.

This section applies to clothing import and export regulatory requirements and non-regulatory requirements of quality inspection sampling is carried out the inspection and quarantine agencies Procedural rules mouth textile quality compliance evaluation should be followed, but also as the import and export of textile production enterprises quality Control guidance documents.

2 Normative references

The following documents for the application of this document is essential. For dated references, only the dated version suitable for use herein Member, undated references, the latest edition (including any amendments) applies to this document.

GB/T 2828.4 Sampling procedures for inspection - Part 4. Sampling procedures for inspection of declared quality level of assessment procedures GB/T 2828.11 Sampling procedures for inspection - Part 11. Sampling procedures for inspection of small claims that the overall level of quality assessment Given program SN/T 3702-1 textile export quality conformity assessment sampling methods - Part 1. General

3.1 Terms and Definitions

SN/T 3702-1 define the following terms and definitions apply to this document.

3.1.1

A class failed Anonconformity Non-poor sewing process requirements that appear on the unit of product, bad ironing, severe contamination, does not match the holes, specifications and other seriously affect the appearance of clothing Efficacy and safety defects.

3.1.2

Class B failed Bnonconformity Non-poor sewing technology requirements appear on unit product, lint, stains and other minor defects affect the appearance of clothing.

3.1.3

A class of nonconforming product Anonconformingitem Per unit of product in more than one class A and failed, it may also contain Class B failed.

3.1.4

Class B non-conforming product Bnonconformingitem Per unit of product in more than one

class B and unqualified, non-A class failed.

3.1.5

Declared quality level Verification overall percentage of unqualified or allowed number of rejects.