

ICS 75.020
CCS E 13

SY

**INDUSTRY STANDARD OF THE
PEOPLE'S REPUBLIC OF CHINA**

SY/T 5247-2008

5357-1999; SY/T 5409-1991; SY/T 5410-1991; SY/T 5558-1992; SY/T 5780-1993; SY/T 5910-1994; SY/T 6049-1994

**Recommended handling methods of downhole problems in
drilling**

钻井井下故障处理推荐做法
(English Translation)

Issued on: June 16, 2008

Implemented on: December 1, 2008

Issued by: National Development and Reform Commission

Table of Contents

What this standard covers	1
Document data	2
Standards quoted by this document	3

What this standard covers

This standard specifies the downhole drilling fault classification and treatment recommended method. This standard adapted to the oil and gas drilling and construction operations downhole failures that occurred during processing.

Document data

International classification (ICS): 75.020.

Chinese classification (CCS): E13.

Estimated length of the Chinese original: 83,879 words.

Supersedes the earlier edition SY/T 5247-1997; SY/T 5248-1991; SY/T 5271-2000; SY/T 5357-1999; SY/T 5409-1991; SY/T 5410-1991; SY/T 5558-1992; SY/T5780-1993; SY/T 5910-1994; SY/T 6049-1994.

Standards quoted by this document

GB 2702; SY/T 5313