Chinastandards.org

SY

INDUSTRY STANDARD OF THE PEOPLE'S REPUBLIC OF CHINA

SY/T 6237-2010

Labour quota for repair of downhole service equipment

井下作业设备修理劳动定额

(English Translation)

Issued on: May 1, 2010 **Implemented on: October 1, 2010**

Issued by: National Energy Administration

Preview: page 1 of 2 shown, full document available. Complete English PDF, instant download:
https://chinastandards.org/standards/sy-t-6237-2010

Chinastandards.org

Table of Contents

Document data

1 Document data

Sector: Petroleum & Gas (industry standard).

Issuing body: National Energy Administration.

Date of issue: 2010-05-01.

Date of implementation: 2010-10-01.

Status: obsolete, replaced by SY/T 6237-2024.

Preview: page 2 of 2 shown, full document available. Complete English PDF, instant download:
https://chinastandards.org/standards/sy-t-6237-2010