

ICS 45.060.20
CCS S 33

TB

**RAILWAY INDUSTRY STANDARD OF THE
PEOPLE'S REPUBLIC OF CHINA**

TB/T 1778-2010

Replacing TB/T 1778-1986; TB/T 2172-1990

Catalogue of rail defects

钢轨伤损分类

(English Translation)

Issued on: October 10, 2010

Implemented on: April 1, 2011

Issued by: Ministry of Railways of the People's Republic of China

Table of Contents

What this standard covers	1
Document data	2
Standards quoted by this document	3

What this standard covers

This standard specifies the various damage on railroad rails classification and numbering, injury is described injury is reason, testing methods and measures to be taken. This standard applies to rail failure statistics, injury is injury is cause analysis and information processing. This standard does not apply to rail failure following circumstances: a) by rail cutting, forging, machining, etc., made of rail parts, such as turnouts (switch rail, wing rail), guard rail, rail and other secondary contraction regulator, b) non-rail damage caused by traffic accidents or disasters damaged rail, c) other than those specified in this standard test with a small amount of special materials or special section of the special rail.

Document data

International classification (ICS): 45.060.20.

Chinese classification (CCS): S33.

Estimated length of the Chinese original: 40,454 words.

Supersedes the earlier edition TB/T 1778-1986; TB/T 2172-1990.

Standards quoted by this document

UIC 712-2002