Chinastandards.org

ICS 91.060.50
CCS Q71

WB

# WB/T 1048-2012

## Repair, replacement and return specification of wood door

木质门修理、更换和退货规范

**(English Translation)**

**Issued on: March 24, 2012** **Implemented on: July 1, 2012**

**Issued by: National Development and Reform Commission of the People's Republic of China**

Preview: page 1 of 3 shown, 5 in the full document. Complete English PDF, instant download:
https://chinastandards.org/standards/wb-t-1048-2012

Chinastandards.org

# Table of Contents

Foreword
1 Scope
2 Normative references
3 Terms and definitions
4 General requirements
4.1 Repair
4.2 Replacement

## Foreword

This standard was drafted in accordance with the rules given in GB/T 1.1-2009.

This standard proposed by the China Federation of Logistics and Purchasing and centralized.

## 1 Scope

This standard specifies the basic requirements for the repair, replacement and return of indoor wooden doors used under normal maintenance conditions.

This standard applies to the normal maintenance conditions used indoor wood door warranty inspection, but also can be used as a basis for evaluating the quality of the warranty.

## 2 Normative references

The following documents for the application of this document is essential. For dated references, only the dated version applies to this article Pieces. For undated references, the latest edition (including all amendments) applies to this document.

WB/T 1024-2006 wooden door

## 3 Terms and definitions

WB/T 1024-2006 defined and the following terms and definitions apply to this document.

Warranty warrantyperiod Production side to give the user free maintenance time.

Door hardware door'shardware in the wooden door to play a role in the role of metal parts.



Preview: page 2 of 3 shown, 5 in the full document. Complete English PDF, instant download:
https://chinastandards.org/standards/wb-t-1048-2012

Closure surface wear closedsurfaceattrition Doors and side frames, doors and doors due to gaps between the gap caused by small deformation caused by the mutual contact of the lateral scratches.

Light transmission slit transmittanceslit; diaphanousseam the door can not cover all the door leaf and the resulting gap.

After-salesservice

After the sale of products, to meet the needs of users, suppliers and users to exchange results of the activities.

### 4.1 Repair

In line with the general quality of the warranty issue, repair should be based. Homework to site operations, back home operations, supplemented.

### 4.2 Replacement

If the product can not be repaired during the warranty period and meets the replacement conditions, it should be replaced.



Preview: page 3 of 3 shown, 5 in the full document. Complete English PDF, instant download:
https://chinastandards.org/standards/wb-t-1048-2012