Chinastandards.org

YB

INDUSTRY STANDARD OF THE PEOPLE'S REPUBLIC OF CHINA

YB/T 951-1981

Ultrasonic rail flaw detection method

(English Translation)

Preview: page 1 of 2 shown, full document available. Complete English PDF, instant download:
https://chinastandards.org/standards/yb-t-951-1981

Chinastandards.org

Table of Contents

Document data

1 Document data

Sector: Ferrous Metallurgy (industry standard).

Status: obsolete, replaced by YB/T 951-2003.

Preview: page 2 of 2 shown, full document available. Complete English PDF, instant download:
https://chinastandards.org/standards/yb-t-951-1981